




www.lamaneta.com
SERVICE SHEETS

BSA SERVICE SHEET No. 501

Revised January, 1957

"D" Group Engine and Gearbox (Exploded View)



NOTE.—On DI engines after 1954, and all D3 engines, the offside Crankshaft Oil Seal is placed next to the flywheel instead of between the two bearings.

B.S.A. MOTOR CYCLES LIMITED, Service Dept., Birmingham, 11
(PRINTED IN ENGLAND)