




SERVICE SHEETS

www.lamaneta.com

BSA SERVICE SHEET No. 808


Oct., 1948
Reprinted Oct., 1957

A, B and M Group Models WIRING DIAGRAMS (NEGATIVE EARTH)



Numbers indicate cable identification colours. See key.

C10 and C11 Models WIRING DIAGRAM (NEGATIVE EARTH)



Numbers indicate cable identification colours. See key.